

**CERTAIN 2015 YZ250F
FACTORY MODIFICATION CAMPAIGN – Engine Balancer Gear Failure**
Yamaha Technical Bulletin M2014-020R

Affected Models:

CG34C-10721~10792	CG34C-11921~11970
CG34C-10881~10900	CG34C-12011~12060
CG34C-10961~11000	CG34C-12101~12150
CG34C-11081~11130	CG34C-12191~12240
CG34C-11291~11370	CG34C-12281~12330
CG34C-11431~11450	CG34C-12371~12435
CG34C-11541~11610	CG34C-12461~12500
CG34C-11651~11678	CG34C-12502~12586
CG34C-11701~11730	
CG34C-11791~11830	

The reason for this recall:

In affected motorcycles, the engine's balancer weight gear and balancer shaft gear were made of material that does not meet design specifications. As a result, the gears could break during operation which would cause the engine to lock up, which could cause a crash with injury or death.

What Yamaha and your dealer will do:

To correct this defect, your authorized Yamaha dealer will replace the balancer weight gear and balancer shaft gear with new ones of the correct material. The service takes about 2 hours, but be aware that your Yamaha dealer may need to keep your YZ for longer depending upon their current service schedule. There will be no charge to you for this procedure.

What you should do now:

Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your motorcycle for this service. If possible, take a copy of this notice with you when you take in your motorcycle. You should not ride your affected YZ250F motorcycle shown above until this modification is performed. If you are unable to return to the Yamaha dealer who sold you the motorcycle, this service will be performed by any authorized Yamaha motorcycle dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the "Find a Dealer" section of this website.