

**All 2014 AND CERTAIN 2015 SR10 (“SRViper”) SNOWMOBILES
FACTORY MODIFICATION CAMPAIGN – Fuel Hose Joint**

Yamaha Technical Bulletin S2014-003R

Affected Models:

2014

SR10REB 8JP00-0000101~0000499

SR10XSEL 8JR00-0000103~0000954

SR10XSER 8JR00-0000957~0001718

SR10RSEL 8JW00-0000111~0000870

SR10LEB 8JX00-0000101~0000870

SR10LSER 8JY00-0000101~0000707

SR10LSEL 8JY00-0000708~0001383

2015

SR10LSFO 8JY20-0000101~0000300

The reason for this recall:

In affected snowmobiles, there is the possibility that clamps on fuel hose joints may have been installed slightly out of position during manufacturing. If clamps are not correctly positioned, fuel might leak from the joints while the fuel system is pressurized during snowmobile operation. A fuel leak increases the risk of a fire that could result in injury or death.

What Yamaha and your dealer will do:

To correct this defect, your authorized Yamaha dealer will inspect the fuel delivery system and, if an incorrectly positioned clamp is found, replace the fuel hose assembly. The service takes about 20 minutes, but be aware that your Yamaha snowmobile dealer may need to keep your SRViper for several hours to allow time for repair depending upon their current service schedule. There will be no charge to you for this procedure.

What you should do now:

Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your snowmobile for this service. If possible, take a copy of this notice with you when you take in your snowmobile. You should not ride your 2014 or affected 2015 SRViper snowmobile shown above until this modification is performed. If you are unable to return to the Yamaha dealer who sold you the snowmobile, this service will be performed by any authorized Yamaha snowmobile dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the “Find a Dealer” section of this website.