

**CERTAIN 2015 Viking VI, Viking VI Hunter, Viking VI EPS, and Viking VI EPS Hunter model (YXC700)
Side X Side Vehicles**

FACTORY MODIFICATION CAMPAIGN – Rear Steel Wheels

Yamaha Technical Bulletin SXS2015-002R

Affected Models:

Viking VI (YXC700DF)

AM75Y-100101~100676

Viking VI Hunter (YXC700DHFH)

AM80Y-100101~100484

Viking VI EPS (YXC700PF)

AM76Y-100101~101700

Viking VI EPS Hunter (YXC700PHFH)

AM82Y-100101~101142

The reason for this recall:

In affected vehicles, the rear wheel nuts can potentially loosen over time due to an incorrect taper specification of the steel rear wheel where the wheel nuts contact the inner wheel panel. If this occurs, the rear wheels could loosen and cause a wobble from the rear end or the rear wheels could come off. These conditions would adversely affect handling and could result in a crash with injury or death.

What Yamaha and your dealer will do:

Your Yamaha dealer will replace both steel rear wheels with new ones that have the correct taper specification. There will be no charge to you for this procedure.

What you should do now:

Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your Viking VI for this service. If possible, take a copy of this notice with you when you take in your vehicle. You should not drive your affected Viking VI shown above until this modification is performed. If you are unable to return to the Yamaha dealer who sold you the vehicle, this service will be performed by any authorized Yamaha Side X Side dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the “Find a Dealer” section of this website.