

2011 FJR13AAS/AASC MODELS
FACTORY MODIFICATION CAMPAIGN – Front Brake Switch
Yamaha Technical Bulletin M2011-004R

Yamaha Motor Corporation, U.S.A. has decided that a defect which relates to motor vehicle safety exists in certain 2011 FJR13AAS and AASC motorcycles. A bulletin was originally issued on July 22, 2011.

Affected Models:

2011 FJR13AAS
RP15E-0007504~0007734

2011 FJR13AASC
RP15Y-0001311~0001345

The reason for this recall: On affected motorcycles, the brake light may not illuminate when the front brake lever is applied because the activating mechanism in the front brake switch can bind. If the brake light does not come on to alert other drivers when the motorcycle operator applies only the front brake, there could be a crash resulting in injury or death.

What Yamaha and your dealer will do: To correct this defect, your authorized Yamaha dealer will install a new front brake switch. There will be no charge to you for this procedure. Installing the new front brake switch takes 15 minutes, although your dealer may need to keep your motorcycle longer depending upon their schedule.

What you should do now: Do not operate your motorcycle until this modification is performed. If you are unable to return to the Yamaha dealer who sold you the motorcycle, this service will be performed by any authorized Yamaha Motorcycle dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the "Find a Dealer" section of this website.