

**CERTAIN 2015-2016 YZF-R3F/G MODELS
FACTORY MODIFICATION CAMPAIGN – Clutch Pressure Plate and Oil Pump
Yamaha Technical Bulletin M2016-005R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that defects which relate to motor vehicle safety exists in certain 2015-2016 YZF-R3F/G models.

Affected Models

2015-2016 YZF-R3F/G

PID Range

RH06Y-0001001~0012320

The reason for this recall:

In affected motorcycles, when the clutch is operated frequently, the clutch pressure plate bearing may break due to insufficient load rating of the bearing. This could cause the clutch to fail to operate so the transmission will not shift properly. In addition, in affected motorcycles, oil pressure may not be properly regulated due to an improper oil relief valve design in the oil pump, which can excessively stress the oil pump drive gear. In the worst case, the gear may break which could result in engine seizure from lack of oil supply. Either of these conditions could cause loss of control that could result in a crash with injury or death.

What Yamaha and your dealer will do:

To correct these defects, your authorized Yamaha dealer will replace the clutch pressure plate assembly and oil pump assembly with parts of a different design. These procedures take about 2 hours to do but be aware that your Yamaha dealer may need to keep your motorcycle longer depending upon their current service schedule. **There will be no charge to you for this procedure.**

What you should do now:

Please call your Yamaha dealer to make a service appointment to have these procedures performed. At that same time, you can find out how long they expect to keep your motorcycle for this service. If possible, take a copy of this notice with you when you take in your motorcycle. You should not ride your affected 2015 or YZF-R3 motorcycle until these modifications are performed. If you are unable to return to the Yamaha dealer who sold you the motorcycle, this service will be performed by any authorized Yamaha Motorcycle dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the “Find a Dealer” section of this website.